ELECTRIC CIRCUIT DIAGRAM OF ACTUATOR WITH DOUBLE TRAVEL SWITCHES AND ANGULAR ENCODER



M - inductive motor
C - capacitor
WO, WZ - travel switch for opening and closing
WOP, WZP - overload switch for opening and closing
WO1, WZ1 - additional travel switch for opening and closing
EPO angular encoder
ZS-30-feeder 230V AC with signal conversion
R overload output resistance

ELECTRIC CIRCUIT DIAGRAM OF ACTUATOR WITH DOUBLE TRAVEL SWITCHES AND DOUBLE POTENTIOMETER



M - inductive motor
C - capacitor
WO, WZ - travel switch for opening and closing
WOP, WZP - overload switch for opening and closing
WO1, WZ1 - additional travel switch for opening and closing
H brake
Px2 double potentiometer